Weathertzsiton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH3114/1Work Order Type: WeatherizationAudit Name: 13013SH3114

CLIENT INFORMATION

Client ID: 13013SH3114

<u>AGENCY INFORMATION</u>

Client ID: 13013SH3114

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: GAILLARD, GREG Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client ID: 13013SH3114

1	Measure 1 Infilt	ration Redctn			Componen	its			Inspected
C	DOOR S REPLAC ASPP K	ER STRIP DOOR FRT, SWEEP FRT, SIDE,FUR CE BROKEN PANE WD ITCHEN, BATH,WASHI CE ATTIC ACCESS COM	NACE CLO #9-30X12 NG MACH	OSET	E,CLOSET				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 2 Repl Comment REPLAC 3 TONS	ace A/C CE CENTRAL AIR SYS	ГЕМ СОМ						Inspected
C	Comment REPLAC 3 TONS	CE CENTRAL AIR SYS		PLETE	Estimated	<u> </u>		Actual	
T C C	Comment REPLAC 3 TONS Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected
T C C	Comment REPLAC 3 TONS	Description / Comment		PLETE	Estimated	<u> </u>	Qty	Actual	
# 1	Comment REPLAC 3 TONS Material / Labor	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
<i>I C</i> # 1 2	Comment REPLAC 3 TONS Material / Labor Cooling Equipmen	Description / Comment Central A/C -	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
<i>I C</i> # 1 2	Comment REPLAC 3 TONS Material / Labor Cooling Equipmen Labor	Description / Comment Central A/C -	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
<i>I C</i> # 1 2	Comment REPLAC 3 TONS Material / Labor Cooling Equipmen Labor	Description / Comment Central A/C -	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
<i>I C</i> # 1 2	Comment REPLAC 3 TONS Material / Labor Cooling Equipmen Labor	Description / Comment Central A/C -	Units Each Each	Qty 1 1	Estimated	<u> </u>		Actual	
# 1 2 C	Comment REPLAC 3 TONS Material / Labor Cooling Equipmen Labor	Description / Comment Central A/C -	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

	Measure 3 Stori	m Windows			Componen			Antoni	Inspected
4	Material / Labor	December 10 manager	Heite		Estimated	 -		Actual	Total
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	Each	1					
2	Labor	Storm Window	Each	1					
C	Other Detail						1		
] []		
]	Cub Total	
_				Measur	e Sub Total:			Sub Total:	
	Measure 4 Replanda Comment REPLAC 80,000 E	CE HEATING SYSTEM	COMPLE		Componen				Inspected
					Estimated			Actual	
	Material / Labor	Description / Comment	Units 	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipmen	REPLACE HTG. SYSTEMS	Each	1					
2	Labor	REPLACE HTG. SYSTEMS	Each	1					
c	Other Detail	0.0.2.m0							
Ī									
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								

Measure 5 CO	MONITOR NEEDED			Componer	its			Inspected
Comment QTY 2								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO MONITOR NEEDED	Each	2					
2 Labor	CO MONITOR NEEDED	Each	2					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
EXH	NONOPERATIONAL KIT AUST FAN L VENTED VENT A HOO			Componer	ıts			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	FIX NONOPERATIONAL KITCHEN EXHAUST FAN	Each	1					
2 Labor	FIX NONOPERATIONAL KITCHEN EXHAUST FAN	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

ı		CTICE LEAD SAFE THERIZATION (WALLS	5)		Componen	ts		1	Inspected
C	omment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	PRACTICE LEAD SAFE WEATHERIZATION (WALLS	Each	1					
2	Labor	PRACTICE LEAD SAFE WEATHERIZATION (WALLS	Each	1					
C	Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
	Measure 8 Pres	sureRelief Piping Need	ded		Componen				Inspected
C			ded <i>Unit</i> s		Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected
<i>C</i>	omment	Description / Comment		Qty 1	Estimated	<u>'</u>	Qty	Actual	
C #	Comment Material / Labor	Description / Comment	Units	Qty	Estimated	<u>'</u>	Qty	Actual	
c # 1	Comment Material / Labor Health and Safety	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
c # 1	Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
c # 1	Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
c # 1	Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	Qty 1 1	Estimated	<u>'</u>		Actual	
c # 1	Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	Qty 1 1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost	

Client ID: 13013SH3114

DOE Weatherization Assistant Version 8.6.0 Page 5 of 5